



WHITE



BLACK



M: 80% Y: 94%



M: 100% Y: 100%

CAUTION: Turn off power before use.

- Strip stranded wires 12.5 mm (0.49").
- Pretwisting unnecessary.
Hold stripped wires together with ends even (lead stranded wires slightly).
- Align any frayed strands or conductors.
- Screw on connector—push wires firmly into connector when starting.
- To be sold only with installation instructions.

LISTED FOR USE WITH
COPPER TO COPPER

Insulation operating temperature:
105°C (221°F) Max.

623-003



Twist-on Wire Connectors

Quantity: 100



22-14 AWG; 600V Max.

Listed as splicing wire connectors
on the following stranded wire combinations:
Voltage: 600V Max.

| | |
|-------------------------|-------------------------|
| 1 #18 w/ 2 #14 | 1 #22 w/ 1 #18 w/ 1 #16 |
| 1 to 3 #20 w/ 2 #14 | 1 to 3 #20 w/ 1 #16 |
| 1 to 3 #22 w/ 2 #14 | 1 to 3 #22 w/ 1 #16 |
| 2 #14 | 2 to 5 #18 |
| 1 or 2 #16 w/ 1 #14 | 1 #20 w/ 4 #18 |
| 1 #18 w/ 1 #16 w/ 1 #14 | 2 #22 w/ 4 #18 |
| 1 to 3 #18 w/ 1 #14 | 1 or 2 #20 w/ 3 #18 |
| 1 to 4 #20 w/ 1 #14 | 1 or 2 #22 w/ 3 #18 |
| 1 to 3 #22 w/ 1 #14 | 1 or 2 #20 w/ 2 #18 |
| 1 #14 w/ 4 #16 | 1 to 3 #22 w/ 2 #18 |
| 1 #22 w/ 4 #16 | 1 to 4 #20 w/ 1 #18 |
| 2 to 4 #16 | 1 #22 w/ 1 #20 w/ 1 #18 |
| 1 #18 w/ 3 #16 | 1 to 5 #22 w/ 1 #18 |
| 1 or 2 #20 w/ 3 #16 | 3 to 5 #20 |
| 1 or 2 #22 w/ 3 #16 | 1 #22 w/ 4 #20 |
| 2 or 3 #18 w/ 2 #16 | 2 or 3 #22 w/ 2 #20 |
| 1 to 3 #20 w/ 2 #16 | 4 #22 w/ 1 #20 |
| 1 to 3 #22 w/ 2 #16 | 5 #22 |
| 1 to 4 #18 w/ 1 #16 | 1 or 2 #22 w/ 3 #18 |



Made in China



63 mm

203 mm