



WHITE



BLACK



M: 25% Y: 100%



M: 100% Y: 100%

CAUTION: Turn off power before use.

1. Strip stranded wires 13 mm (0.51").
2. Pretwisting unnecessary.
Hold stripped wires together with ends even (lead stranded wires slightly).
3. Align any frayed strands or conductors.
4. Screw on connector—push wires firmly into connector when starting.
5. To be sold only with installation instructions.

623-004



Listed as splicing wire connectors on the following stranded wire combinations:
Voltage: 600V Max.

Twist-on Wire Connectors

Quantity: 100

| | |
|---------------------|---------------------|
| 1 #14 w/ 1 #10 | 1 or 2 #16 w/ 3 #14 |
| 1 #18 w/ 2 #10 | 1 or 2 #18 w/ 3 #14 |
| 2 #12 | 1 #18 w/ 4 #14 |
| 2 or 3 #14 | 4 #18 w/ 1 #16 |
| 5 #16 | 3 or 4 #18 w/ 2 #16 |
| 5 to 7 #18 | 1 or 3 #18 w/ 3 #16 |
| 1 or 2 #14 w/ 1 #12 | 2 #18 w/ 2 to 4 #16 |
| 1 to 3 #16 w/ 1 #12 | 1 #18 w/ 4 #16 |
| 1 to 3 #18 w/ 1 #12 | |
| 1 #16 w/ 2 #12 | |
| 1 to 4 #16 w/ 1 #14 | |
| 1 to 4 #18 w/ 1 #14 | |
| 1 to 3 #16 w/ 2 #14 | |
| 1 to 4 #18 w/ 2 #14 | |

LISTED FOR USE WITH
COPPER TO COPPER

Insulation operating temperature:
105°C (221°F) Max.



18-10 AWG; 600V Max.



Made in China



63 mm

191 mm