

WIRING INSTRUCTIONS

TITLE




5378-20 1/2" HAMMER-DRILL

MILWAUKEE ELECTRIC TOOL CORP. 13135 WEST LISBON RD. BROOKFIELD, WIS.

DATE
Oct. 2004

BULLETIN
58-01-1150

**SEE THE BACK OF THIS BULLETIN
FOR INSTRUCTIONS ON HOW TO CONNECT
WIRES TO SWITCH NO. 23-66-1692.**



WIRING SPECIFICATIONS


Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation
1	Black	18	6.25	Leadwire assembly 23-94-1045
2	Red	18	4.75	Leadwire assembly 23-94-1060
3	Purple / Blue	18	2.75	Leadwire assembly 23-94-1055
4	Yellow	18	5.25	Leadwire assembly 23-94-1050
5	Black	Cord	3.50	Component of cord set
6	White	Cord	2.25	Component of cord set
7	Black / Grey	Brush	2.25	
8	Yellow	Brush	4.25	

NOTE:
All leads must be held to $\pm 1/16"$.
All lead lengths are before stripping.




TERMINAL DESCRIPTION

Code	Part No.	Qty.

CONNECTOR DESCRIPTION



**SEE THE FRONT OF THIS BULLETIN
FOR INSTRUCTIONS ON HOW TO CONNECT WIRES
TO SWITCH NO. 23-66-1690.**



WIRING SPECIFICATIONS

Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation
1	Black	18	6.25	Leadwire assembly 23-94-1045
2	Red	18	4.75	Leadwire assembly 23-94-1060
3	Purple / Blue	18	2.75	Leadwire assembly 23-94-1055
4	Yellow	18	5.25	Leadwire assembly 23-94-1050
5	Black	Cord	3.50	Component of cord set
6	White	Cord	2.25	Component of cord set
7	Black / Grey	Brush	2.25	
8	Yellow	Brush	4.25	

NOTE:
All leads must be held to $\pm 1/16"$.
All lead lengths are before stripping.

TERMINAL DESCRIPTION

Code	Part No.	Qty.

CONNECTOR DESCRIPTION

--	--	--